TORY 23372 30 30 N SS STATE STATE	DATE 2318Z 30 JUN 65	TOPSEC	RET	Idea	120 111 12
TOR: 2335Z 30 JUN 65 TOR: 2335Z 30 JUN 65 OSPI - 20 IN-954 OPRIORITY INFO CITE	<u> </u>	5X1A	[7]	N+el DFA RB	स्पर्यक्तः र प्रदर्भकाष्ट्रम् स्वरं विद्यालयो अस्ति एतः प्रदारम् अस्य स्वरंभक्षः स्वरंभवस्य स्वरंभवस्य राज्यः १९ प्रदानः । स्वरंभागां स्वरंभवित राज्यसम्बद्धाः अस्य स्वरंभक्षः स्वरंभक्षः स्वरंभक्षः स्वरंभक्षः र राज्यसम्बद
TO PRIORITY INFO CITE INFO			er en	11.D	PRIORITY
PRIORITY INFO CITE LINES		65	051	91-20	IN-95437
	PRIORITY	INFO	egibbooksis katalu waa kasa yoo ii ii isaa waxaa ka ahaa ka ahaa ka ahaa ka ahaa ka ahaa ahaa ahaa ahaa ahaa a	CITE	2
ATTENTION:	1Δ				

- 1. CAMERA 119 WAS USED IN MISSION 02450 FLOWN ON 30 APRIL 1965.
 PROCESSING WAS ACCOMPLISHED IN THE FIELD.
 - 2. ORIGINAL NEGATIVE:
 - A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION WAS GOOD. ;
- 8. 9R SIDE: A PROCESSING DENSITY CHANGE IS APPARENT IN FRAME 612. THERE IS A HEAT SPLICE BETWEEN FRAMES 674/675. SCOTCH TAPE WAS USED FOR A SPLICE BETWEEN FRAMES 1281/1282.
- C. 9L SIDE: FRAMES 134 TO 137 ARE CRIMPED AND ARE ACCOMPANIED WITH PROCESSING MARKS. A PROCESSING DENSITY CHANGE IS PRESENT IN FRAME 773. THE SPLICES BETWEEN FRAMES 1099 TO 1100 AND 1185 TO 1186 APPEAR TO BE MADE WITH SCOTCH TAPE.
- D. BOTH SIDES: ROLLER CHATTER IS PRESENT ON THE INBOARD RP KB KB KB THROUGHOUT THE MISSION. IRREGULAR PLUS DENSITY MARKS AND WC DB STREAKS APPEAR INTERMITTENTLY IN THE MISSION. THE LAST TITLED FRIME

Approved For Release 2003/03/28: CIA-RDP66B00597R000400020005-5

25X1A

4867 (IN 95437) TOPSECRET

PAGE 2

ON BOTH SIDES IS FRAME 1304.

- E. THERE WERE NO MAJOR CAMERA OR PROCESSING MALFUNCTIONS.
- 3. POSITIVE:
 - A. PI SUITABILITY WAS GOOD.
 - B. PRINTING AND PROCESSING WAS ADEQUATE.
 - C. THE APPROXIMATE CLOUD COVER IS 35 PERCENT.

END OF MESSAGE